

# Oil Field Environmental Incident Summary

**Incident:** 20150508104128      **Date/Time of Notice:** 05/08/2015 10:41

**Responsible Party:** HESS CORPORATION

**Well Operator:** HESS CORPORATION

**Well Name:** CMU Satellite 6

**Field Name:** CAPA

**Well File #:**

**Date Incident:** 5/7/2015      **Time Incident:** 09:30      **Facility ID Number:** 400486-02

**County:** WILLIAMS      **Twp:** 155      **Rng:** 95      **Sec:** 20      **Qtr:** NE NW

**Location Description:** The landowner stated that the land is used for pasture. The impacted area from the pictures taken after the incident look like the land may have been cultivated.

**Submitted By:** Alex Beach

**Received By:**

**Contact Person:** Jason Henry  
3015 16TH ST SW STE 20  
MINOT, ND 58701

**General Land Use:** Other - Described Above

**Affected Medium:** Topsoil

**Distance Nearest Occupied Building:** 1.3 Mile

**Distance Nearest Water Well:** 1.3 Mile

**Type of Incident:** Treater Popoff

**Release Contained in Dike:** No

**Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	5	Barrels				

Brine

Other

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

There is no immediate risk to report at this time

**Areal Extent:**

**Potential Environmental Impacts:**

The approximate 5 bbl. release impacted an estimated 293'x81' area south of the building (where the secondary pop-off was located). Of that area, an estimated area 262'x81' was past the fence line and into the landowner's field. Some pooling of oil occurred outside the building and ran off location to the

**Action Taken or Planned:**

A vacuum truck was called to remove the pooled crude oil on location and the cleanup process will be initiated. The affected material will be cleaned up and disposed of at an approved waste facility. Investigation is ongoing.

**Wastes Disposal Location:** The affected material will be cleaned up and disposed of at an approved waste facility.

**Agencies Involved:****Updates**

---

**Date:** 5/8/2015      **Status:** Reviewed - Follow-up Required

**Author:** Stockdill, Scott

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

According to the incident summary, this spill impacted areas off of location. Followup is necessary.

---

**Date:** 5/12/2015      **Status:** Inspection

**Author:** Martin, Russell

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

5/12/2015 at 14:56, on location. Personnel on site currently working on cleanup. Impacted areas south and east of treater building. South side has been scraped up; east side is still impacted. Crews currently building a ramp down to east side due to steepness of facility slope, so impacted dirt can be placed in trucks for removal.

---

**Date:** 7/16/2015    **Status:** Inspection

**Author:** Martin, Russell

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

7/16/2015 at 13:12, on location. East side has been scraped, and reseeded. New vegetation here is not as uniform, but no visible staining within or outside of scraped area. New vegetation on South side is more uniform.